



## **Cleaning and Care**

All OCA covers are extremely tough and designed to withstand the harshest of environments. Inevitably they will get dirty, and you may want to clean them. Most dirt can be removed during routine boat cleaning with fresh water and a soft brush. For more stubborn marks please follow the cleaning instructions below.

Please remember:

- Mould does not exist unless dirt is present, so keep your covers clean.
- If you do not rinse the salt out of your cover on a regular basis (6/6 below) as per the instructions, it will build up inside on the felt backing and may scratch your motor.
- Please follow the <u>6/6 rule</u>, wash/ rinse every <u>6 weeks or 6 outings</u>.
- Please be aware that the printing may become damaged if rubbed aggressively or bunched up when cleaned or stored.

**DO NOT** wash your cover/s in a washing machine or with standard detergents, this removes the chemicals used to protect the fabric from environmental damage (UV, salt, bird droppings etc.) and damages the printing. We recommend that the covers are rinsed by hand in fresh water with a little silk/ wool detergent and left to air dry.

When washing covers with any print please avoid rubbing or folding the covers along any printed area. This can cause marks to appear on the print.

## DO NOT USE A JET WASHER OR HIGH-PRESSURE WATER ON THE COVERS.

## White Covers

Please note that white covers will show dirt much more than other colours. If washed regularly the UV resistance and any print colours will be degraded faster than normal. This is not covered under our product warranty (manufacturing fault claims not affected).

## Re Proofing

The water repellent performance can be improved by an application of AQUA-TITE® GREEN or AERO 303 water repellents. Please follow the instructions that accompany these treatments but **DO NOT** let the re proofer touch the decals.

**NOTE:-** If you do not maintain your covers in accordance with the care instructions you may void your warranty. We operate rigorous QC methods and history shows that 99% of all damaged covers are due to improper care.

Please remember that the cover's job is to protect the motor from damage so has a 'sacrificial' element to it.